Declass	ified in Part - Sanitized Copy	Approved for Re	lease 2013/12/16 :	CIA-RDP67B00	329R0001001	170049-3
'IATE	1417Z Ø3 JUL 63	The control of the co	R F T	2 3	Control of the second s	D 1/11 D 3
Control of the second s	DIRECTOR					itell
FROM :	KW CABLE					
action:	OSA 1-15 ROUTINE				e carried no.	
nifo 8	S/C 16			Company and more substituting and more substituting		50X1
	TOR 1528Z 23 JUL 63				IN 8199	6
TO	ADIC	INFO		GITE	CABLE 01	49
	OXCART OPS					
	FOLLOWING COMMENTS CONCERN DUAL SUIT FLT OF					50X1
	IN ACFT	24 ON 2 JUL	. 63. TIME IN	FLT 1 HR 4	MIN.	50X1
	TIME IN SUIT 3 HRS. COMBINED OXYGEN CONSUMPTION AT 26M CABIN					
	ALTITUDE: 35.8 LPM.					
	10	SUIT COMFOR	TABLE. HELME	T DOES NOT		50X1
	PROVIDE SUFFICIENT UPWARD VISION. INTERNAL OXYGEN LEADS BECAME					
	UNCOMFORTABLE DURING FLT. FACIAL REFLECTION PROBLEM.					
	2. REPETITION OF PREVIOUS PROBLEMS:					50X1
	REFLECTION, HELMET WEIGHT, AND DISCOMFORT OF EAR PHONES.					
	END OF MESSAGE					. •
		400 1 10 W 0 4 10 W				4
			AUTH: HR 70-	CLASS. A TED To: TS S C Date:	<del></del>	

SECRET

GROUP 1 iduded from endematic descriptionism declarationism